

- A. LIGHT NO. 12 VERY DIM.
- B. LIGHT NO. 10 WAS WIRED INCORRECT AND SHOULD HAVE BEEN NO. 9.
- C. LIGHT NO. 9 SHOULD HAVE BEEN NO. 8.
- D. LIGHT NO. 8 SHOULD HAVE BEEN NO. 10.
- 2. BINARY INDEX LIGHTS AND CAMERA NUMBER ON AFT CAMERA FAILED AFTER PRE-FLIGHT. THIS GREATLY COMPLICATED BINARY READOUT.
 - 3. NO OTHER LIGHT FAILURES OCCURRED.

END OF MESSAGE

